

Message

From: Chris Parks [cparks@iwmconsult.com]
Sent: 4/4/2019 9:27:16 PM
To: Bury, Carolyn [bury.carolyn@epa.gov]; jbian@amphenol-aa.com
CC: Brad Gentry [bgentry@iwmconsult.com]; Neal, Conor [Neal.Conor@epa.gov]; Sundar, Bhooma [sundar.bhooma@epa.gov]; Caudill, Motria [caudill.motria@epa.gov]
Subject: Confidential: Draft data from Design-Level Data Soil Investigation
Attachments: Draft Design-Level Data Soil Analytical Results Table.pdf; Soil PCE Below Sewer.pdf; Soil PCE Above Sewer.pdf; Soil PCE Base of Unit B.pdf; Soil TCE Unit B Base.pdf; Soil TCE Above Sewer.pdf; Soil TCE Below Sewer.pdf; Draft Unit C Structural Contour Map.pdf

Carolyn,

Please see the attached Draft Design-Level Data Soil Sampling Analytical Results. I have also attached 3 draft PCE in soil maps, 3 draft TCE in soil maps, and a draft Unit C topographic map.

As you can see in the soil maps which display data immediately 1' above/1' below the sewer, the off-site PCE/TCE impacts are limited, as most concentrations are near the PCE/TCE migration to groundwater screening level. Additionally, impacts along the sewer at the base of Unit B are elevated in a couple of areas, but these areas will likely not be able to be excavated due to their total depth/depth below the water table.

Following review of the Unit C Topography, there appear to be some troughs/lobes; however, based on the lack of observed NAPL during off-site soil boring installation and generally low absorbed concentrations, it appears that PCE/TCE impacts leached to groundwater from cracks in the sanitary sewer line and then migrated vertically.

Please let me know if you have any questions.

Sincerely,
 Chris



Christopher D. Parks, LPG
 Senior Project Manager
 7428 Rockville Road
 Indianapolis, IN 46214
 Direct: (317) 968-9260
 Mobile: (317) 847-2600
 Office: (317) 347-1111 x 127
 Fax: (317) 347-9326